






PHASE 0 - Marking and Drilling of Holes

Isometric view of the beam: top view

Axonometric view of the beam: bottom view



Longitudinal section S1-S1 of the beam along the axis  
(scale 1:20)




DESCRIPTION OF WORKS - PHASE 0


Once the layout, type, and quantity of fabrics to be applied have been defined, before proceeding with the installation, follow the following preliminary operational steps:

- 0.1 After removing any existing plaster, carry out mechanical cleaning of the substrate. Always check for possible concrete degradation by performing carbonation depth tests and chloride penetration tests. Conduct rebar detection surveys (pacometric investigations) to minimize interference between the existing reinforcement and the new connectors (See Phase 1);
- 0.2 Preparation of the reinforced concrete substrate with a possible repair cycle for damaged concrete. For details, refer to the reference drawings. The application surface must not be "smooth" but "rough," with a roughness index between 0.3 – 0.5 mm. It must be free of oils, grease, and/or release agents. Any surface cleaning must be done mechanically, preferably by sandblasting. To verify the suitability of the surface, refer to the guidelines of the ICRI – International Concrete Repair Institute, specifically classes CSP2, CSP3, CSP4, and CSP5 for in-situ laminates, and CSP6 for prefabricated reinforcements;
- 0.3 Marking of the holes to be made, according to the graphical layout shown in this document;
- 0.4 Drilling of  $\varnothing$  12/14 mm holes for anchoring the connectors, with a countersink of  $\varnothing$  16 mm and a countersink depth greater than 10 mm. Use a rotary-only hammer drill (no percussion). In the case of non-through connectors, the hole depth must be equal to the length of the connector plus 10 mm;
- 0.5 Cleaning of holes from any debris by blowing with a compressor or brushing with a brush, while simultaneously vacuuming the dust with an appropriate vacuum cleaner.



Hole execution



Section



Plan view



- Legend**
- $L_c$  = connector length;
  - $L_{c,v}$  = projection of the connector relative to the vertical axis;
  - $L_{c,o}$  = projection of the connector relative to the horizontal axis;
  - $L_f$  = hole length.

HOLE TABLE ON BEAMS

Characteristics
Parameters
$w = 5 \varnothing$
$z = 200 - 5 \varnothing$
$r = b_{f,2} / 2$
$t = b_{f,1} / 2$

Note:















- ◆ Marking of connector holes  
For anchoring the reinforcement ends for bending
- ◆ ◆ Marking of connector holes  
For shear reinforcement

The measurements are expressed in mm unless otherwise specified





PHASE 0 - Marking and drilling of holes (scale 1:20)



characteristics							
View	Symbol	d. holes	Ø holes	Chamfer	Inclination	Hole length	Parameters
V1-V1	●	$b_{f,1} - b_{f,2}$	12 / 14	> 16	45°	$200 + 10 \leq L_{fo} \leq \frac{3}{4} X + 10$	$w = 5 \varnothing$
V2-V2	●	$b_{f,1} - b_{f,2}$					$z = 200 - 5 \varnothing$
V2-V2	◆	$b_{f,2}$				$200 + 10 \leq L_{fo} \leq h_{tr}$	$r = b_{f,2}$
V1-V1 V2-V2	◆	$b_{f,2}$					$t = b_{f,1}/2$

**Note 1**

$b_{f,1}$  : width of the reinforcement fabric outside the column;  
 $b_{f,2}$  : width of the reinforcement fabric inside the thickness of the column.

**Note 2**

For the tracking of the connectors in node k, use a criterion similar to the one described for node i.

The measurements are expressed in mm unless otherwise specified.







**PHASE 1 - Anchoring of connectors in C.F.R.P.**


**Axonometric view of the beam: top view**

**Axonometric view of the beam: bottom view**



**Longitudinal section of the beam along the axis**

(scale 1:20)



**DESCRIPTION OF WORKS - PHASE 1**

Once the layout, type, and quantity of reinforcement to be applied have been defined, wait for the repair mortar to cure in accordance with the product technical data sheets. In any case, check the moisture content of the substrate, which must be less than 10%, including by drilling a hole to a depth equal to the thickness of the repair mortar.

The installation of the passing through connectors must be carried out after the preliminary surface preparation and hole drilling phases (See Phase 0), proceeding with the following operational steps:


- 1.1 After thoroughly cleaning the holes (see Phase 0.5) and the surfaces, apply the epoxy primer type **FB-RC01** according to the instructions in the technical data sheet. Wait 1 hour and do not exceed 3 hours. During this waiting period, proceed with the installation of the passing through connectors following the instructions in the subsequent steps, after first applying a layer of impregnating resin **FB-RC02** only at the location of the fiber spreading;
- 1.2 Injection of resin for anchoring bars (connectors) type **FB-RC30/3**;
- 1.3 Anchoring of single-ended bowed bars (non-passing through connectors), positions 1-2-3, type **FB-TUP10-CHT1A Ø10**, inclined at 45°, without performing the bowing. Anchoring of double-ended bowed bars (passing through connectors), position 4, type **FB-TUP10-CHT2A Ø10**, inclined at 45°, ensuring one end of the bar is protected using plastic wrap and wrapped with iron wire. The anchoring operation must be carried out by rotating the bar to ensure perfect adhesion of the resin both to the bar itself and to the inner surface of the hole;
- 1.4 Bowing at a 60° angle on the bars in positions 1-2-3 installed in Phase 1.3, and impregnation of the same with resin type **FB-RC02**. Apply the same procedure to the bars in position 4 (bars bowed on both ends).

**Phases scheme**

Installation of passing through connectors.

**Note:**

- Connectors for anchoring the reinforcement ends for bending
- Connectors for shear reinforcement.



**MATERIAL IDENTIFICATION**













- (A1) FB-TUP10-CHT1A (Bowed bars in C.F.R.P.)
- (A2) FB-TUP10-CHT2A (Bowed bars in C.F.R.P.)
- (B-C) FB-GV.....-..... (Unidirectional fabric in C.F.R.P.)
- (P1) FB-RC01 (Epoxy resin - Primer)
- (P2) FB-RC02 (Epoxy resin - Impregnant)
- (P3) FB-RC30/3 (Epoxy resin - Anchoring)

The measurements are expressed in mm unless otherwise specified  
For the materials table, refer to drawing FRP22.





PHASE 1 - - Anchoring of CFRP connectors. (scale 1:20)



**Legend :**  
 $n_{fabrics INT}$ : n° of fabrics contained within the width of the column;  
 $n_{fabrics EXT}$ : n° of fabrics external to the width of the column;  
 $n_{nodes}$ : n° of nodes;  
 $n_{nodes INT}$ : n° of internal nodes.



CFRP CONNECTORS TABLE					
identification		characteristics			
Material	Symbol	N. connectors	Ø connectors	length of connectors	Position
(A1) - pos.1		$(n_{nodes} - n_{nodes INT}) \cdot (n_{fabrics EXT} \cdot n_{nodes} + n_{fabrics INT} \cdot (n_{nodes} + n_{nodes INT}))$	10	$200 \leq L_{co} \leq \frac{3}{4} X$	Top face of the beam
(A1) - pos.2		$2 \cdot (n_{fabrics EXT} + n_{fabrics INT} \cdot (n_{nodes} - 1))$			Bottom face of the beam
(A1) - pos.3		$2 \cdot (n_{nodes} + 1) \cdot n_{fabrics INT}$			Bottom face of the beam
(A1) - pos.4		$4 \cdot (n_{nodes} + n_{nodes INT}) \cdot n_{fabrics INT}$		$L_{co,4} \geq \frac{3}{4} n_{tr}$	Bottom face and top face of the beam

The measurements are expressed in mm unless otherwise specified.  
For the materials table, refer to drawing FRP22.






PHASE 2 - Installation of reinforcement systems



Longitudinal section of the beam along the axis  
(scale 1:20)



DESCRIPTION OF WORKS - PHASE 2

Once the layout, type, and quantity of fabrics to be applied have been defined, the installation must be carried out according to the following operational steps:


2.1 After applying a layer of impregnating epoxy resin **FB-RC02**, install unidirectional C.F.R.P. fabrics, type **FB-GV.....-.....**, longitudinally on the bottom surface (intrados) of the beam, ensuring no formation of wrinkles, folds, or air pockets. Use a bubble-breaking roller to facilitate this process. After laying the fabrics, apply a second layer of impregnating resin **FB-RC02** and continue rolling with the bubble-breaking roller until the fibers are fully impregnated;

2.2 Apply the same procedure for unidirectional C.F.R.P. fabrics, type **FB-GV.....-.....**, on the top surface (extrados) of the beam. Repeat steps 2.1 and 2.2 if additional layers are required according to the design.;

2.3 Apply quartz sand evenly over the surface of the resin composite while it is still fresh, to allow the finishing plaster to adhere.

Phases scheme

Installation of fabrics on the top surface of the beam



MATERIAL IDENTIFICATION












- (A1) FB-TUP10-CHT1A (Bowed bars in C.F.R.P.)
- (A2) FB-TUP10-CHT2A (Bowed bars in C.F.R.P.)
- (B-C) FB-GV.....-..... (Unidirectional fabric in C.F.R.P.)
- (P1) FB-RC01 (Epoxy resin - Primer)
- (P2) FB-RC02 (Epoxy resin - Impregnating agent)
- (P3) FB-RC30/3 (Epoxy resin - Anchoring)

Dimensions are given in mm unless otherwise specified. For the materials table, refer to drawing FRP22.





PHASE 2 - Installation of reinforcement systems (scale 1:20)







CFRP REINFORCEMENT TABLE					
identification		caratteristiche			
Material	Symbol	N. layers	Geometric parameters	Fabric length $L_f$	Position
(C)		to be defined	$b_f, t_f$	$(L_{beam}/3 - X/2) \cdot 2 \cdot n_{fabrics INT} \cdot (n_{nodes} - 1)$	Top surface of the beam, along the width of the column
(C)				$L_{beam}/3 \cdot 2 \cdot n_{fabrics INT} \cdot (n_{nodes} - 1)$	Top surface of the beam, outside the column
(C)				$L_{beam} \cdot n_{spans} - n_{columns} \cdot X$	Bottom surface of the beam, along the width of the column
(C)				$L_{beam} \cdot n_{spans}$	Bottom surface of the beam, outside the column

**Note:**  
 $n_{fabrics INT}$ : number of fabrics contained within the width of the column.

The measurements are expressed in mm unless otherwise specified.  
For the materials table, refer to drawing FRP22.



**PHASE 0** - marking phase (drawings FRP 01.a - 01.b)**PHASE 1** - Installation phase of the connection/anchoring system (Drawings FRP 01.c - 01.d)**PHASE 2** - Installation phase of the reinforcement (Drawings FRP 01.e - 01.f)