




PHASE 1 Installation of the mesh and connectors on the extrados, and drilling of holes.




PHASE 2 Installation of angles, connectors, and patches.




LAYOUT SCHEME OF INSTALLATION OF CONNECTORS N.4/m²
(scale 1:25)




PHASE 3 Application of mortar on the extrados



PHASE 4 Drilling and installation of GFRP connector into hardened plaster followed by filling.



PARTICULAR DETAIL



The measurements are expressed in centimeters unless otherwise specified
For the connector layout diagram and materials table, please refer to table CRM19

